






# Application problems with new thread milling cutters

Problem	Possible causes	Solution
<b>1 Thread produced is too large or too small</b> 	<ul style="list-style-type: none"> <li>Incorrect radius in CNC program and therefore milling of incorrect circle</li> </ul>	<ul style="list-style-type: none"> <li>Correct milling radius until thread is dimensionally correct</li> </ul>
<b>2 Thread not cylindrical</b> 	<ul style="list-style-type: none"> <li>Feed rate too high</li> <li>Synchronous milling path with long threads</li> </ul>	<ul style="list-style-type: none"> <li>Reduce feed rate</li> <li>Modify milling direction to opposite direction</li> </ul>
<b>3 Thread surface not according to requirements, chatter marks</b> 	<ul style="list-style-type: none"> <li>Cutting speed too high</li> <li>Insufficient tool or workpiece clamping</li> </ul>	<ul style="list-style-type: none"> <li>Adjust cutting speed</li> <li>Check tool and workpiece clamping</li> </ul>
<b>4 Tool breakage</b> 	<ul style="list-style-type: none"> <li>CNC program error</li> <li>Cutting rates too high</li> </ul>	<ul style="list-style-type: none"> <li>Check CNC program</li> <li>Adjust cutting rates</li> </ul>
<b>5 Tool life insufficient</b>	<ul style="list-style-type: none"> <li>Cutting rates too high</li> <li>Tool applied uncoated</li> <li>Insufficient lubrication and chip evacuation</li> </ul>	<ul style="list-style-type: none"> <li>Adjust cutting rates</li> <li>Apply coated tool</li> <li>Improve lubrication, coolant delivery via the spindle</li> </ul>
<b>6 Tool breakage with drill/milling cutter</b> 	<ul style="list-style-type: none"> <li>Chip problems when drilling</li> <li>Feed rates too high when drilling</li> </ul>	<ul style="list-style-type: none"> <li>Apply tool with IC</li> <li>Incorporate pecking cycles</li> </ul>