

3M Versaflo™

M-929

Shaded Peel-Off Visor Cover

User Instructions

IMPORTANT: Before use, the wearer must read and understand these *User Instructions*. Keep these *User Instructions* for reference.

98-0060-0234-3
34-8716-3227-8



⚠ WARNING

This component is part of a respiratory protection system that helps protect Against certain airborne contaminants. **Misuse may result in sickness or death.** For proper use, see supervisor, *User Instructions* or call 3M in U.S.A., 1-800-243-4630. In Canada, call Technical Service at 1-800-267-4414.

Contact Information

Before use, read all instructions and warnings for this product and all instructions and warnings for the M-Series headgear. Keep these *User Instructions* for reference. If you have questions regarding this product contact 3M Technical Service in your region.

In United States:

Website: www.3M.com/PPESafety
Technical Service: 1-800-243-4630

In Canada:

Website: www.3M.com/CA/occsafety
Technical Service: 1-800-267-4414

Description

The 3M™ Versaflo™ Shaded Peel-Off Visor Cover M-929 is an optional accessory for the 3M™ Versaflo™ M-Series Headgear. The peel-off is optimized for the M-927 Premium Visor. Use of the shaded peel-off cover M-929 on the uncoated M-925 visor may leave residue upon removal.

The shaded peel-off cover M-929 complies with the shade W3.0 transmission requirements listed in Table 6 of the American National Standards Institute Eye and Face Protection standard ANSI Z87.1-2010. The peel-off cover is intended for use in torch brazing and soldering applications. For additional information on the technical

specifications, consult the M-929 Technical Specifications Sheet available at www.3M.com/PPEsafety.

WARNING

Do not use the Shaded Peel-Off Cover (M-929) for welding. The Shaded Peel-Off Cover (M-929) will not protect the wearer's eyes from the harmful level of visible light, ultra-violet radiation (UV), and infrared radiation (IR) resulting from gas and arc welding processes. **Misuse may result in permanent eye injury and vision loss.** For welding use an ANSI Z87.1 complaint welding helmet with an appropriate filter lens for the specific welding process.

Only use the Shaded Peel-Off Cover (M-929) on 3M™ Versaflo™ M-Series Headgear. Do not use on any other headgear including faceshields and eyewear. **Misuse may result in permanent eye injury and vision loss.**

Assembly

To attach the peel-off cover to the outside of the M-927 visor:

1. Before installing the peel-off cover, ensure the visor is clean and dry.
2. Remove the paper backing from the adhesive on the edges of the cover.
3. Center the cover over the outside of the visor and press the edges with the adhesive coating against the visor.
4. If the peel-off is being attached to a visor not yet installed into the M-Series Headgear Assembly, insert the visor into the headgear following the procedures in the M-Series Headgear *User Instructions*.
5. Verify the peel-off is centered on the visor and there is minimal gap between the visor frame assembly and the peel-off cover.
6. If the peel-off is not centered on the visor, remove the peel-off and repeat steps 1-5 above with a new peel-off cover.
7. Read completely and follow the *User Instructions* for the M-Series Headgear and your 3M supplied air device or powered air purifying respirator to complete system assembly and performance checks.

NOTE: Use only one peel-off cover at a time. Do not stack multiple M-929 shaded peel-off covers on the M-Series visor. **Do not** use any other peel-off cover in combination with the M-929 including the clear peel-off visor covers M-926 and M-928.

Inspection and Maintenance

Carefully inspect the peel-off for damage before each use including holes, tearing, ripping, peeling, discoloration, and hazing. **If you discover any signs of damage, remove headgear from use and replace the peel-off visor cover with a new one. Failure to do so may affect performance and reduce the degree of protection provided.**

Storage and Disposal

Before use, store the M-929 Shaded Peel-Off covers in original unopened packaging in a clean area that is protected from contamination, damage, dirt, debris, product distortion, and direct sunlight. Do not store next to furnaces, ovens, or other sources of high heat. When stored in accordance with the recommended storage conditions listed in the M-Series Headgear *User Instructions*, product may be used until “use by” date specified on packaging. Always inspect product before use. Dispose of product according to local regulations.

FOR MORE INFORMATION

In United States, contact:

Website: www.3M.com/PPESafety

Technical Assistance: 1-800-243-4630

For other 3M products:

1-800-3M-HELPS or 1-651-737-6501

RENSEIGNEMENTS SUPPLÉMENTAIRES

Aux États-Unis :

Internet : www.3M.com/PPESafety

Assistance technique : 1 800 243-4630

Autres produits 3M :

1 800 364-3577 ou 1 651 737-6501

PARA MAYORES INFORMES

En Estados Unidos:

Sitio Web: www.3M.com/PPESafety

Soporte técnico: 1-800-243-4630

Para otros productos 3M:

1-800-3M-HELPS o 1-651-737-6501

PARA MAIS INFORMAÇÕES

Nos Estados Unidos, entre em contato com:

Website: www.3M.com/OccSafety

Assistência Técnica: 1-800-243-4630

Para outros produtos 3M:

1-800-3M-HELPS ou 1-651-737-6501

3M Personal Safety Division

3M Center, Building 0235-02-W-70

St. Paul, MN 55144-1000

© 3M 2015. All rights reserved.

3M and Versaflo are trademarks of 3M Company, used under license in Canada.