CERTIFICATE OF COMPLIANCE

Certificate Number 20201016- R9700

Report Reference R9700

Issue Date 2020-October-16

Issued to: 3M COMPANY 3M FIRE PROTECTION PRODUCTS

3M CENTER

SAINT PAUL, MN 55144-1001 USA

This certificate confirms that representative samples of

Fill, Void or Cavity Materials

Have been investigated by UL in accordance with the

Standard(s) indicated on this Certificate.

Standard(s) for Safety: ANSI/UL 1479, "Fire Tests of Penetration Firestops"

Fourth Edition

Additional Information: See the UL Online Certifications Directory at

https://iq.ulprospector.com for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.





UL LLC





CERTIFICATE OF COMPLIANCE

Certificate Number 20

20201016-R9700

Report Reference

R9700

Issue Date

2020-October-16

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

3M Fire Barrier Rated Foam, FIP 1-Step for use in Through-Penetration Firestop System Nos. C-AJ-0140, C-AJ-0153, C-AJ-1628, C-AJ-1629, C-AJ-1668, C-AJ-3321, C-AJ-3339, C-AJ-4098, C-AJ-4109, C-AJ-5347, C-AJ-8217, W-J-0023, W-J-0025, W-J-0026, W-J-1231, W-J-1232, W-J-3177, W-J-4073, W-J-4074, W-J-7134, W-J-7135, W-J-7136, W-J-7137, W-J-8052, W-L-0045, W-L-0049, W-L-0050, W-L-1478, W-L-1479, W-L-1520, W-L-1526, W-L-3347, W-L-4082, W-L-4084, W-L-4088, W-L-4089, W-L-4090, W-L-7225, W-L-7226, W-L-7227, W-L-7228, W-L-8100, W-L-8106.

Ba Willy

Bruce Mahrenholz Director North

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, pleas contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

