

Refill for PIG® HazMat Spill Kit in 50-Gallon Container

RFL365 Absorbs up to 27 gal., Absorbs Acids; Bases; Unknowns

Don't be caught with an empty spill kit when you need it most! Keep a refill handy to instantly replace used contents.

- Packed to refill your PIG HazMat Spill Kit in 50-Gallon Overpack Salvage Drum or 50-Gallon Container
- PIG HazMat Socks stop spreading spills; PIG HazMat Pads and Pillows absorb quickly
- PIG HazMat Absorbents are specially treated for unsurpassed performance with concentrated corrosives, such as 98% sulfuric acid and 30% sodium hydroxide
- Temporary disposal bags help make cleanup easier
- Tamperproof seals help prevent pilfering of spill response supplies
- Only PIG Spill Kit Refills feature PIG Absorbents proven for rapid response



Specifications

Fluid Absorbed	Acids; Bases; Unknowns
Absorbency	Up to 27 gal.
Sold as	1 each
Weight	33 lbs.
# per Pallet	12
Composition	Mats, Socks, Dikes & Pillows - Polypropylene
Includes	5 - ext. dia. 3" x 46" L PIG® HazMat Chemical Absorbent Sock (124CR) 5 - ext. dia. 3" x 10' L PIG® HazMat Chemical Absorbent Sock (PIG301) 4 - 17" W x 16" L x 2" H PIG® HazMat Chemical Absorbent Pillow (HR7015) 40 - 15" W x 20" L PIG® HazMat Mat Pad (MAT301) 5 - 36" W x 60" H Polyethylene Disposal Bags (BAG201-L) 6 - 2" W x 6" L Tamperproof Seal Label (LBL100) 1 - Instructions 56 - 11.875" W x 13" L PIG® PR40 All-Purpose Wipers (WIP310)

Metric Equivalent

Absorbency	Up to 102.2 L
Weight	15 kg

Technical Information

Technical Documents

[PIG Hazardous Chemical Absorbents](#)

[Instructions for PIG HazMat Absorbents](#)

[PIG® HAZ-MAT Absorbents](#)

Disclaimers

HAZ-MAT Notice

To ensure effectiveness and your safety, we recommend that you conduct compatibility and absorption testing of your chemicals with PIG® HAZ-MAT products prior to purchase. If you have any questions or need samples to test, please call Technical Services.



One Pork Avenue • Tipton, PA 16684-0304

1-855-493-4647 • Fax: 1-800-621-7447 • newpig.com • hothogs@newpig.com